



**CONFIDENTIAL**  
CONFIDENTIAL

50X1-HUM

especially critical; these conditions are approximately characterized in practice by various quantities of Reynolds numbers and, consequently, by various linear velocities. It is found that the most important factor is the actual design and construction of the gas-supply ducts and cross sections, it being noted that most presentday designs of coking ovens are defective because the currents are hindered by the sharp angles in the narrow input openings.

- E N D -

- 2 -

CONFIDENTIAL

**CONFIDENTIAL**